

Figure 1: Uploading FIRMWARE.DLF.

## Firmware update procedure

1. Connect to ADSLRouter via Ethernet cable and log-in Router.
2. Click the “Reset to Factory Default” on admin privilege and reboot.
3. Enable the FTP Server on Misc configuration and save.
4. Click Code image update in admin privilege
  - (a) Click Browse button in right page
  - (b) Choose FIRMWARE.DLF then click upload button. The message “you must reboot the system now” will appear.
  - (c) Click the reboot button now!!




Figure 2: Uploading bootrom.dlf.

5. After the router rebooted successfully:
  - (a) Click code image update in admin privilege.
  - (b) Click Browse button in right page.
  - (c) Choose bootrom.dlf then click upload button. The system will be rebooted.




Figure 3: The end result should look like this.